Monthly Report for the month of - November. Jobcode: 012-16-000001

BRUHATH BENGALURU MAHANAGARA PALIKE - DAILY STREET LIGHT MAINTENANCE REPORT

VIJAYALAKSHMI ASSOCIATES, Bangalore.

DATE 01-11-2019 - 30-11-2019 AREA: Shetty halli - Abbigere PACKAGE D1-~~D2~~ WARD No. 12

SL No.	POLE NO	REPLACEMENT DETAILS AND QUANTITIES																				Twin Twis Wire	Remarks
		40 WATT F T L				250 WATT S V				400 WATT M H					125 WATT M V			LED LIGHT				
		Tube	Chk	Sl	Rl Hld	Lamp	Chk	IG	Hid	Lamp	Chk	IG	Hid	Cpr	Lamp	Chk	IG	24W	65W	110W		
1	01-11-2019	2	2	2	1	5	3	2	1														
2	02-11-2019	2	2	1	2	4	3	4															
3	03-11-2019					5	3	3	3														
4	04-11-2019	2		2	2	4	2	3	1													5MTS	
5	05-11-2019					5	5	3	2													3MTS	
6	06-11-2019					3	3	2	2														
7	07-11-2019	2	1	2	1	5	2	3	2														
8	08-11-2019					3	3	1	2														
9	09-11-2019					5	4	1	2														
10	10-11-2019	3	3	3	2	3	2	3	1													5MTS	
11	11-11-2019	3	2	2	1	3	2	1	1														
12	12-11-2019					5	4	2	1														
13	13-11-2019					3	2	3	2													2MTS	
14	14-11-2019					5	3	4	2														
15	15-11-2019	1	1	1		5	3	2	2													5MTS	
16	16-11-2019					3	3	2	1														
17	17-11-2019	2	2	2	1	4	2	2															
18	18-11-2019					3	3	4	2														
19	19-11-2019					4	2	3	2														
20	20-11-2019					4	2	3	2														
21	21-11-2019	3	2	3	1	4	3	2	1														
22	22-11-2019					5	2	1	2														
23	23-11-2019					4	1	2	1														
24	24-11-2019					6	2	3	2														
25	25-11-2019	2	2	2	2	3	2	2	1													2MTS	
26	26-11-2019					4	3	2	1														
27	27-11-2019	2	1	2	2	3	2	1	1														
28	28-11-2019					5	3	4	2													5MTS	
29	29-11-2019					4	3	3	1														
30	30-11-2019	3	1	2	1	4	2	2															
31																							
		27	19	24	16	124	79	73	44													27MTS	

Prepared by : Jayamma Thar Reddy

Checked by : Manjegowda

bruhath Bangalore Mahanagara Palike
Dasarahalli Zone, Bangalore

Scanned by CamScanner

Monthly Report for the month of - October.

BRUHATH BENGALURU MAHANAGARA PALIKE - DAILY STREET LIGHT MAINTENANCE REPORT

VIJAYALAKSHMI ASSOCIATES, Bangalore.

DATE 01-10-2019. To 31-10-2019 AREA: Shettyhally - Abbigere PACKAGE: P1 WARD No. 12

SL. No.	POLE NO.	REPLACEMENT DETAILS AND QUANTITIES																			Twin Twis Wire	Remarks
		40 WATT F.T.L				250 WATT S.V.				400 WATT M.H					125 WATT M.V			LED LIGHT				
		Tube	Chk	St	Rl Hld	Lamp	Chk	IG	Hld	Lamp	Chk	IG	Hld	Cpr	Lamp	Chk	IG	24W	65W	110W		
1	01-10-2019	2	1	2	1	3	3	2	1													
2	02-10-2019					5	1	4	1												5MTS	
3	03-10-2019					5	3	3	2													
4	04-10-2019					4	2	2	2													
5	05-10-2019	2	2	1		5	3	2	1												2MTS	
6	06-10-2019	2	1	2	1	3	2	4	3													
7	07-10-2019					4	1	4	1													
8	08-10-2019					5	2	3	2												5MTS	
9	09-10-2019					4	2	3	2													
10	10-10-2019	2	2	2	2	2	3	2	2													
11	11-10-2019	1		1	1	4	3	4	2													
12	12-10-2019					5	2	2	2												3MTS	
13	13-10-2019					4	2	4	1													
14	14-10-2019	1	1	1	1	3	2	3	2													
15	15-10-2019	4	1	2	2	2	2	1	2													
16	16-10-2019	2	2	2		5	2	4	2												5MTS	
17	17-10-2019					4	3	2	2													
18	18-10-2019					5	2	4	1													
19	19-10-2019					6	2	3	2													
20	20-10-2019	2	2	2		3	2	3	1													
21	21-10-2019					5	2	3	3													
22	22-10-2019	4	2	3	2	4	2	4	1													
23	23-10-2019					3	2	4	1													
24	24-10-2019	2	2	2	2	4	4	3	2												5MTS	
25	25-10-2019					5	1	2	3													
26	26-10-2019					2	2	4	3													
27	27-10-2019					6	4	2	3													
28	28-10-2019	3	3	2	1	4	3	2	1													
29	29-10-2019	2	2	2	1	3	3	2	2													
30	30-10-2019					4	3	2	2													
31	31-10-2019					5	4	3	2													
		29	19	24	14	125	74	90	57												25MTS	

Prepared by: J. Reddy

Checked by:

ASST. EXECUTIVE ENGINEER (Ele)
Bruhath Bangalore Mahanagara Palike
Dasarahalli Zone, Bangalore

Scanned by CamScanner

Monthly Report for the month of September.

BRUHATH BENGALURU MAHANAGARA PALIKE - DAILY STREET LIGHT MAINTENANCE REPORT

VIJAYALAKSHMI ASSOCIATES, Bangalore.

DATE 01-09-2019 TO 30-09-2019 AREA Chetty halli - Abbigere PACKAGE P1- WARD No. 12

SL No.	POLE NO	REPLACEMENT DETAILS AND QUANTITIES																				Remarks
		40 WATT F.T.L				250 WATT S.V				400 WATT M.H					125 WATT M.V			LED LIGHT			Twin Twis Wire	
		Tube	Chk	Sl	Rl Hld	Lamp	Chk	IG	Hid	Lamp	Chk	IG	Hid	Cpr	Lamp	Chk	IG	24W	65W	110W		
1	01-09-2019	2	1	2	1	3	2	3	1													
2	02-09-2019					5	3	4	1													
3	03-09-2019					5	3	3	2													
4	04-09-2019					5	2	2	2													
5	05-09-2019	2	2	2		5	2	2	2													
6	06-09-2019	2	2	1	2	4	2	2	2													
7	07-09-2019					5	2	3	2													
8	08-09-2019					3	2	4	2													
9	09-09-2019					5	3	2	2													
10	10-09-2019					4	3	3	1													
11	11-09-2019	3	2	1		5	4	1	2													
12	12-09-2019					4	2	4	2													
13	13-09-2019					3	2	2	2													
14	14-09-2019					3	3	5	1													
15	15-09-2019	3	2	1	1	2	3	4	1													
16	16-09-2019					4	2	1	3													
17	17-09-2019					5	2	3	2													
18	18-09-2019	3	2	2		2	2	3	1												5 MTS	
19	19-09-2019					3	2	2	2												2 MTS	
20	20-09-2019					4	2	3	3													
21	21-09-2019	2	1	2	1	3	2	4	1													
22	22-09-2019					3	1	2	2													
23	23-09-2019	4	3	2	2	5	2	4	1													
24	24-09-2019					2	2	2	1												5 MTS	
25	25-09-2019					4	2	3	1												5 MTS	
26	26-09-2019					4	2	3	1													
27	27-09-2019					5	3	2	2													
28	28-09-2019					4	1	2	2												3 MTS	
29	29-09-2019					3	2	4	1												2 MTS	
30	30-09-2019					4	2	3	2													
31																						
		21	15	13	7	116	67	85	50												22 MTS	

Prepared by : I Reddy

Checked by :

ASST. EXECUTIVE ENGINEER (Ele)
Bruhath Bangalore Mahanagara Palike

Scanned by CamScanner

monthly. Report for the month of - August.

BRUHATH BENGALURU MAHANAGARA PALIKE - DAILY STREET LIGHT MAINTENANCE REPORT

VIJAYALAKSHMI ASSOCIATES, Bangalore.

DATE 01-08-2019 TO 31-08-2019 AREA: Shetty halli - Hebbagodi PACKAGE: D1. ~~D2~~ WARD No. 12

SL No.	POLE NO	REPLACEMENT DETAILS AND QUANTITIES																				Remarks
		40 WATT F.T.L				250 WATT S.V.				400 WATT M.H					125 WATT M.V			LED LIGHT			Twin Twis Wire	
		Tube	Chk	St	Rt Hld.	Lamp	Chk	IG	Hid	Lamp	Chk	IG	Hid	Cpr	Lamp	Chk	IG	24W	65W	110W		
1	01-08-2019	1	1	1		6	4	3	3													
2	02-08-2019	3	2	1		5	2	4	1													
3	03-08-2019	1		1		5	3	5	1													
4	04-08-2019	1	1	1		4	2	4	3													
5	05-08-2019					5	2	3	2												5MTS	
6	06-08-2019	2	2	2		5	1	2	1												2MTS	
7	07-08-2019	2	2	2		5	2	3	1													
8	08-08-2019					6	6	4	3												5MTS	
9	09-08-2019	1	1	1		4	5	3	2													
10	10-08-2019	1	1	1	1	4	4	3	3													
11	11-08-2019	1		1		2	5	2	4													
12	12-08-2019	1	1	1	1	6	5	4	4													
13	13-08-2019					5	3	3	3													
14	14-08-2019	1	1	1		5	3	3	1													
15	15-08-2019	2	1	2		6	5	3	5												4MTS	
16	16-08-2019					5	4	2	1													
17	17-08-2019					4	5	2	3													
18	18-08-2019					3	2	3	1													
	19-08-2019	1	1	1		5	5	4	3													
	20-08-2019					4	4	3	1													
	21-08-2019					5	5	3	3													
	22-08-2019					6	5	4	4													
	23-08-2019					4	5	4	3												5MTS	
	24-08-2019					4	5	3	2													
	25-08-2019	1	1	1		4	4	3	4													
	26-08-2019					4	2	3	2													
	27-08-2019	4	2	1		5	2	1	1												5MTS	
	28-08-2019					5	3	4	2													
	29-08-2019					4	3	4	1													
	30-08-2019	2	1	2	1	3	2	2	1													
	31-08-2019					3	2	5	1													
		25	18	20	3	141	108	104	70												26MTS	

Jagannatha Reddy

Checked by : Manjegowda

ASST. EXECUTIVE ENGINEER (Ele)
Bruhath Bangalore Mahanagara Pal
Dasarahalli Zone

Scanned by CamScanner